

Service Bulletin

20-046

August 14, 2020 Version 2

Safety Recall: 2018-19 HR-V Fuel Pump Motor

This service bulletin was replaced by the following:

- 20-052, Safety Recall: 2018-19 HR-V AWD Fuel Pump Motor
- 20-053, Safety Recall: 2018-19 HR-V 2WD Fuel Pump Motor

CUSTOMER INFORMATION: The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by "do-it-yourselfers," and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Honda automobile dealer.